774522	*		-	TAN		R. A.					
Ph											
Windrush Building O,M, and N	Schedule Home Owner Meeting	Install electric rough- in	Plumbing rough-in	HVAC rough-in	Frame inspection	Insulation	Gypsum Board installation				
Building O											
Unit 655			400								
Unit 653			400								
Unit 651			400								
Unit 649											
Building M											
Unit 637											
Unit 639											
Unit 641											
Unit 643											
Building N											
Unit 647											
Unit 645											
Clubhouse			}								
Laundry Room		400	}								
	•										
	Cabaduled	4	(IP) - In Progress			(C)-Complete					
(TBS) - 10	Be Scheduled		1	No.							

	Windrush Building 0,M, and N	Schedule Home Owner Meeting	Install electric rough- in	Plumbing rough-in	HVAC rough-in	Frame inspection	Insulation				
	Building O										
	Unit 655						Million Control				
	Unit 653										
	Unit 651										
1	Unit 649										
1	Building M										
1	Unit 637										
	Unit 639										
	Unit 641										
	Unit 643										
	Building N										
	Unit 647										
	Unit 645										
	Clubhouse										
۱	Laundry Room										
١											
A											
		1									